



8 June 2020
20-ED-071

Mr. Matt Cogburn
Planning and Management Division
Oklahoma Water Resources Board
3800 North Classen Boulevard
Oklahoma City, OK 73118

RECEIVED

SEP 28 2020

Oklahoma Water Resources Board

CONCRETE

SAND & GRAVEL

STONE

BLOCK

MASONRY

RE: Water Monitoring Plan Report, 1st Quarter 2020, for Dolese Bros. Co. Davis Quarry, Murray County, Oklahoma

Dear Mr. Cogburn:

According to the Oklahoma Water Resources Board's Title 785, Chapter 30, Subchapter 15, Part 4, *Mines with Preexisting Exemptions*, Dolese Bros. Co. Davis Quarry qualifies as a mine with a preexisting exemption. As part of maintaining this exemption status, the regulations require us to do the following:

1. Adopt and implement a plan to monitor and report to the Board the accumulation and disposition of pit water during the previous calendar year;
 - The Davis Quarry has adopted and implemented such a plan, and the tables below serve to report to the Board the accumulation and disposition of pit water during 1st Quarter 2020.
2. Make quarterly and annual reports of the measured or reasonably estimated groundwater and surface water volumes, separately stated, entering the pit, of the water that is diverted from the pit, of the disposition of the water from the pit, and of the consumptive use of the water from the pit on or before the deadlines provided by Title 82 of Oklahoma Statutes, § 1020.2(E)(1);
 - The Davis Quarry has continued to fulfill this obligation by compiling and submitting this 1st Quarter 2020 report. The specific information requested in this section is outlined in the tables shown below.
3. At any time after March 31, 2015, demonstrate to the satisfaction of the Board within the pertinent report or reports that the mine has not consumptively used during the previous twelve-month period, from the mining site, an amount of groundwater which combined with any amounts used from permitted groundwater wells exceeds the MEPS¹. Such demonstration may require providing to the Board a copy of the mine's monitoring plan and all of the data collected and procedures used to support the calculations and results reported.
 - After 31 March 2015, the Davis Quarry will be willing to demonstrate to the Board that the mine site has not consumptively used during the previous twelve-month period from the mining site, an amount of groundwater which combined with any amounts used from permitted groundwater wells exceeds the MEPS. Example calculations used in the First Quarterly Monitoring Report for 2013 have already been submitted to the OWRB for review and analysis.

¹ Mine's Equal Proportionate Share

DOLESE BROS. CO.

20 NW 13th Street • P.O. Box 677

Oklahoma City, OK 73101-0677

405.235.2311

dolese.com

RECEIVED

SEP 28 2020

Mr. Matt Cogburn
Oklahoma Water Resources Board
20-ED-071
Page Two

Water Monitoring Plan Report
1st Quarter 2020
for Dolese Bros. Co. Davis Quarry
Murray County, Oklahoma

Below, in Tables 1, 2, and 3, are shown the 1st Quarter 2020 summary data collected at the Davis Quarry.

Table 1

Accumulation & Disposition of Pit Water during 1st Quarter 2020

	<u>Groundwater</u> Acre-Feet	<u>Surface Water</u> Acre-Feet	<u>Total</u> Acre-Feet
Water Entering The Mine Pit	201.31	116.31	317.62
Water Diverted From The Mine Pit Into Fresh Water Lake	201.31	116.31	317.62
Water Removed From Fresh Water Lake	656.78	625.49	1,282.27
Water Returned To Fresh Water Lake	605.57	576.73	1,182.30
Water Returned To Land Surface Overlying ASA² Basin	136.55	130.04	266.59
Water Consumptively Used	94.27	(See Table 3 for Calculations)	

Table 2

Water Fluctuations in Fresh Water Lake during 1st Quarter 2020

Average Size of Lake	32.98 acres
Loss in Water Elevation	0.03 feet
Loss in Lake Volume	0.99 acre-feet

Table 3

Consumptive Use Summary for 1st Quarter 2020

	<u>Amount of Pit Water Used,</u> Acre-Feet	<u>Groundwater Content,</u> Percent	<u>Groundwater Component,</u> Acre-Feet
1 North Water Well	0.00	All	0.11
2 South Water Well	0.00	All	1.39
3 Material Moisture Hauled from Site	5.99	51.22	3.07
4 Land Application for Roadway Dust Suppression	8.37	51.22	4.29
5 Evaporation from Mine Pit	0.04	63.38	0.03
6 Offsite Dewatering	166.71	51.22	85.39
Total Groundwater Consumption from ASA at Davis Quarry = 94.27 Acre-Feet			

² Arbuckle Simpson Aquifer

SEP 28 2020

Mr. Matt Cogburn
Oklahoma Water Resources Board
20-ED-071
Page Three

Oklahoma Water Resources Board

Water Monitoring Plan Report
1st Quarter 2020
for Dolese Bros. Co. Davis Quarry
Murray County, Oklahoma

Below, in Table 4, please find the Groundwater Rights Summary for the Davis Quarry.

Table 4
Summary of Groundwater Rights for Davis Quarry

<p>From Acreage on the Arbuckle-Simpson Aquifer And Included in the ASA Groundwater Rights</p> <p style="text-align: right;">(1,186 ac. on ASA)*(0.2 ac-ft/acre) = 237.2 acre-feet on the ASA</p>
<p>From Acreage off the Arbuckle-Simpson Aquifer And Excluded from the ASA Groundwater Rights</p> <p style="text-align: right;">(1,630 ac. off ASA)*(2.0 ac-ft/acre) = 3,260* acre-feet off the ASA</p> <p><i>*We have acquired some additional property that is located off the ASA. We have adjusted the figures above to reflect these changes.</i></p>

Based on the plan that we have adopted and implemented to monitor and report the accumulation and disposition of pit water, based on our actual consumptive use of groundwater quantities, and based on the timely submittal of all reports including this 1st Quarter 2020 report, we believe that the Davis Quarry is in full compliance with all of the regulations that allow us to maintain its preexisting exemption.

General Information

Our calculations show that Davis Quarry's total estimated groundwater consumption for 1st Quarter 2020 was 94.27 acre-feet. This equates to about 39.74% of Davis Quarry's Equal Proportionate Share (EPS) for the year.

- The calculations show the groundwater consumption to be this high because plant personnel were required to discharge some water from the Fresh Water Lake (FWL) due to high water conditions accumulated in the Fresh Water Lake at the end of last year and first part of this year. During First Quarter 2020, the FWL was leaking back into the Mine Pit very significantly; consequently, they lowered the adjacent FWL a few feet to reduce the leaking volume and pump hours. Approximately 91% of the groundwater shown to be "consumed" during the quarter was as a result of this off-site dewatering.
- The remaining amount consumed during the quarter (approximately 9% of the total amount consumed) pertains to all other consumptive use activities, which include groundwater usage from two (2) small water wells, material moisture hauled from the site, dust suppression waters, and evaporation of Mine Pit water.

We have 237.2 acre-feet per year of groundwater rights available over the ASA at the Davis Quarry location, but our total available water rights for this site could also include other significant unused groundwater rights that we have at another site that also overlies the ASA in Murray County. These unused groundwater rights equate to approximately 266.6 acre-feet per year from 1,333 acres of land that overlies the ASA. Both the Davis Quarry property and the other land we own are located within the western lobe of the ASA.

RECEIVED

Mr. Matt Cogburn
Oklahoma Water Resources Board
20-ED-071
Page Four

SEP 28 2020

Oklahoma Water Resources Board for Dolese Bros. Co. Davis Quarry
Murray County, Oklahoma

Water Monitoring Plan Report
1st Quarter 2020

During 1st Quarter 2020, the Davis Quarry logged 14.0 inches of rainfall, as measured using rain gauges. The effective runoff into the quarry pits and lakes from these rains was estimated to be only 5.47 inches. Only one of the individual rainfall events during the quarter were greater than 2 inches.

The "calculated" groundwater percentage in the Fresh Water Lake was 51.22% for the 1st Quarter 2020, and storm water comprised the other 48.78%. These percentages vary each quarter primarily because of the fluctuations in rainfall amounts and intensities during each quarter. For instance, during the second quarter of 2019, the groundwater concentration in the FWL was only 9.23% compared to this quarter's concentration of 51.22%. However, we received nearly 22 inches of rain during 2nd Quarter 2019 compared to only 14 inches during the current quarter. More importantly, the estimated runoff into the Mine Pit during the 2nd Quarter 2019 was 11.6 inches—more than double the runoff of the current quarter, which was 5.47 inches. The variation in the groundwater concentrations between 2nd Quarter 2019 and this quarter (9% versus 51%) shows the significant impact of the FWL seepage volume into the Mine Pit on the Mine Pit's groundwater concentration when the quarterly rainfall is rather low.


In the Annual Water Monitoring Reports for this quarry, we have always included more of the details regarding the water calculations and how they were performed, than are shown in the quarterly reports. The Annual Reports also detail how we always try to use the least controversial methods of calculating and estimating groundwater consumption at this facility. Since these detailed explanations were just covered in the Annual Report for 2019, I will not outline them in these upcoming quarterly reports.

As we stated last quarter, water management always has been and continues to be very important to us at Dolese Bros. Co., especially at the Davis Quarry. We understand that the Arbuckle Simpson Aquifer is a unique aquifer that must be protected. Our plant personnel make daily efforts to responsibly manage the waters within our quarry boundaries so that when they return to their nearby homes and properties, these same quality waters will be available for their personal and community uses.

Please contact me if you have any questions or comments concerning this submittal. Thank you.

Sincerely,

DOLESE BROS. CO.



Daniel E. Becker, P.E.
Environmental Engineer

db

cc: Mr. Chris Neel, Oklahoma Water Resources Board

Email: danb@dolese.com
Telephone: 405-297-8266